



A-101, 101 HRA#2

DPD-7227-59
COPY 1 OF 2

OCT 21 3 30 PM '59

File Nr. 6625

P.O. Box 36
Warner Robins, Georgia
20 October 1959

STATINTL



P.O. Box 6057
Mid City, Washington D.C.

Dear Dan:

Reference your DPD-6912-59 dated 9 October 1959.

The problem, as stated in your letter, is difficult to confirm because of the manner in which the Power Supplies were received. This item was superceeded by a new transistorized Power Supply part number MP-10864. At this point, all the Mp-10406 power supplies became obsolete and were recalled by the depot. These obsolete items were returned to with the exception of 2 ea on hand here.

STATINTL

We hope that the following summary of receipts and shipments will clarify this picture.

Receipts of MP-10406

2 ea From R&W on shipper MP-1C (This was a loan and was not charged to equipment requirement No. 3)

12 ea From Washington D.C. on loan basis

1 ea From STATINTL

1 ea From Wright Patterson AFB

16 ea Total Receipts

The one (1) each received from Wright Patterson was shipped to R&W. The Contractor then returned this one (1) each MP-10406 directly to This reduced the quantity that we should be held accountable for to 15 each total.

STATINTL

Further, we did receive two (2) additional MP-10406 from R&W which are not listed above. However, these were received against Work Orders and should not be counted as additional assets. These two were part of the original 15 each received. The fact that they were returned against Work Orders is noted on MP shipping documents 400C and 593C.

The total of 15 each MP-10406 supplied to the depot were shipped to IAC and Del Rio for installation in the articles. When these items were recalled we received ten (10) each back from 4699. Eight of these were shipped direct to Bob Welch and two (2) each were shipped to R&W for re-work. These two which were previously mentioned are on hand at this activity.

There are five each MP-10406 un-accounted for. Some of these were lost in crashes but it is difficult to state the exact quantity due to incomplete crash records during the early part of this program.

As a matter of information, we have received twenty-five (25) each MP-10864 transistorized Power Supplied as specified by Contract A-101.

We will gladly furnish any additional information that you may require.

Sincerely,

STATINTEL

